



Laboratory Corporation of America® Holdings
 PO Box 25249
 Richmond, Virginia 23260
 Telephone: 800-888-8061

Group No. E053031
 Account No. 19519510
 Report Date: 02/25/00

DALE MCGUIRE
 A C M SERVICES CORPORATION

1101 TAFT STREET
 ROCKVILLE, MD 20850

Final Report

Date Received: 02/22/00 Date Sampled: 02/21/00
 Sample Type: 1 - Bulk Sample(s)
 Project: SAM498 PO Number:

Analytical Results

Client No. \ Description	Lab ID	Total Asbestos in Samp	Layer % of Samp	Sample Components	Results per Layer
003	-001	>1-5 %	100	WHITE CHALKY W/WHITE PAPER-LIKE Asbestos found in white chalky only	
				Chrysotile	>1-5 %
				Cellulose	20 %
				Non-fibrous	75 %

Debbie Grady, Analyst

Exhibit 1



ACM Services, Inc.
1101 Tatt Street
Rockville, MD 20850-1311
301-279-0072 or 800-242-7760
Fax 301-279-0272
<http://www.ACMservices.com>

September 11, 2000

John Belferman
21600 Beallsville Road
Barnesville, MD 20838

**RE: Wall and Ceiling Plaster
Sheet Flooring
(ACM #MD5045)**

Dear Mr. Belferman:

Enclosed is the executed copy of the transport and landfill manifest. This document indicates that the disposal of asbestos waste from the above referenced project was properly completed. In addition, enclosed is the third party air monitoring report, which certifies that the air quality was below Environmental Protection Agency, recommended values for reoccupancy.

These are the last documents that you should receive from our office regarding this abatement project. It was a pleasure working with you.

Should you need our services again or require additional information, please feel free to call.

Sincerely,
ACM Services, Inc.

SERVICE TRANSPORT GROUP, INC.



PHONE: (877) 999-9559

BOX 2132, BRISTOL, PA 19007

WASTE SHIPMENT RECORD

S.T.G. # **TR-2773**

NO **50865**

GENERATOR	1. Material Origin Site 21600 Beallsville Road Barnesville, MD 20838		Generator: Name/Address John Belferman 21600 Beallsville Road Barnesville, MD 20838		Generator: Phone # 301-972-7467
	2. Removal Contractor: Name/Address ACM Services, Inc. 1101 Taft Street Rockville, MD 20850-1311				Contractor: Phone # 301-279-0072
	3. Responsible Agency: Name/Address U.S. EPA Region III 1650 Arch Street Philadelphia, PA 19103-2029		4. US DOT Class - FRIABLE ASBESTOS ONLY RQ ASBESTOS, 9, NA 2212, PG III		
	5. Description of Materials Specify Friable or Non-Friable		Containers No.	Type	Total Quantity
	Non-friable Asbestos		21	Bags	2 (yd3)
Friable Asbestos		45	Bags	4.5 (yd3)	
6. Special Handling Instructions 24-hour emergency spill response no. 800-424-9300					
7. Generator Certification: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transport by highway according to the applicable regulations of the Department of Transportation, US E.P.A., and any other state government agency. I certify that the foregoing is true and correct to the best of my knowledge. If the waste shipment is not as I stated, I accept the RETURN of the COMPLETE LOAD to the generator's service location at the generator's expense.					
Printed/Typed Name & Title Dale R. McGuire, Director of Operations			Signature 		Date 8/1/00
TRANSPORTER	8. Transporter 1 (Acknowledgement of Receipt of Materials) *If blank, Transporter 2 serves as sole transporter.				
	Company Name & Address		Signature: _____ Printed Name: _____ Title: _____		Telephone No. _____ Date: _____
	9. Transporter 2 (Acknowledgement of Receipt of Materials) Company Name & Address Service Transport Group, Inc. P.O. Box 2132 Bristol, PA 19007		Signature:  Printed Name: _____ Title: _____		Telephone No. 877-999-9559 Date: 8-3-00
DISPOSAL SITE	10. Discrepancy Indication Space:				
	11. Waste Disposal/Recycling Site Owner or Operator's Certification (Receipt of above Waste Except as Noted in 10)				
	Company Name & Address Greenridge Reclamation R.D. #1, Box 716 Landfill Road Scottdale, PA 15683		Signature: Denise L. Rugg Printed Name: AUG 31 2000 Title: _____		Telephone No. 724-887-9400 Date
Permit No. 100281					

DAILY MONITORING REPORT

Project Name: Barnesville residence

Project Number: 000-1812

Client's Name: ACM Services, Inc.


Date: 3/23/02

Project Address: 21600 Beardsville Road, Barnesville, Md.

Prepared by: E. CURTIS

1. Number of employees present from abatement contractor: 5
2. Number of hours worked by the contractor: 1:00 From: 6:00 To: 7:00
3. Number of air samples taken (excluding blanks and quality control): 4
4. Number of bulk samples taken and where: 1

Sketch area:



AREA UNDER CONTAINMENT

5. Amount and location of asbestos removed: ceiling/wall plaster, mastic
6. Removal methods used: full containment
7. Total number of bags generated: 37
8. Disposal/storage area: ACM Waste truck
9. Air sample results from prior day given to contractor or posted? NO If no, explain: 1st day
10. Special notes: (particular problems, special visits, equipment malfunction, specific non-compliance noted, asbestos disposal, HEPA filter changes, problems with air monitoring results)

10:30 JH on site. Containment already up & set and
calibrate pumps
11:20 Crew begins abatement samples started
1:30 Bag-out and fine cleaning begin
2:15 Encapsulation begins
3:00 Final air sample begin
4:50 Final sample read clearance for teardown begin
5:00 JH departs site

ASBESTOS AIR SAMPLE LOG

Project Name: Beverly, NevadaProject Number: COO-1312Client's Name: ACM SERVICES, INCDate: 08/03/00

Project Address: _____

Prepared by: E. CURTTONSampler: ERIC CURTTONAnalyst: ERIC CURTTONSample Type: PCMFilter Size: 25mm

Sample No.	Pump No.	Flow On (L/min.)	Flow Off (L/min.)	Time On	Time Off	Total Min.	Volume	Fibers/Fields	Fibers/cc	Location
080500 EC01	806	2.5	2.5	11:00	4:30	330	825	$\frac{4}{100}$	<0.01	O.W.A. 2' from clean room entrance
080300 EC02	808	2.5	2.5	11:00	11:30	30	75	$\frac{8}{100}$	<0.02	I.W.A.
080500 EC03	809	2.5	2.5	10:55	2:00	185	4625	$\frac{16}{100}$	<0.11	Personal
080300 EC04	910	12.0	12.0	3:00	4:40	100	1200	$\frac{3}{100}$	<0.01	FINAL
080300 EC05	N/A	N/A	N/A	N/A	N/A	N/A	N.F.O.	N.F.O.	N/A	BLANK # 1 (FIELD)
080300 EC06	N/A	N/A	N/A	N/A	N/A	N/A	N.F.O.	N.F.O.	N/A	BLANK # 2 (Lab)

Analyst Signature: Eric CurttonClayton E. Miller, L.H.
Project Manager

16. Do you have documentation relating to the purchase and/or installation of the product in the property?

☐ Yes ☒ No

If Yes, attach all such documents. If the documents are too voluminous to attach, attach a summary of the documents indicating the name of each document, date of each document, a brief description of the document, the location of the document, and who has possession and control of the document.

If you provide a summary of documents rather than the documents themselves, you are required to consent to the production and release of those documents to Grace upon Grace's further request.

17. If you do not have any such documents, explain why not and indicate who may have possession or control of such documents with respect to the property.

TEXTURED PAINT APPLIED TO SHEETROCK BEFORE I BOUGHT;
BELIEVE APPLIED BY STEWART COLLINS, 20460 OLD
HUNDRED ROAD, POOLESVILLE, MD 20837

18. When did you first know of the presence of asbestos in the property of the Grace product for which you are making this claim?

2000

Year

Please attach all documents relating or referring to the presence of asbestos in the property for which you are making this claim. If the documents are too voluminous to attach, attach a summary of the documents indicating the name of each document, date of each document, a brief description of the document, the location of the document, and who has possession and control of the document.

If you provide a summary of documents rather than the documents themselves, you are required to consent to the production and release of those documents to Grace upon Grace's further request.

19. How did you first learn of the presence of asbestos in the property of the Grace product for which you are making this claim?

BEFORE REMOVING PAINTED WALLBOARD, TOOK PAINT SAMPLE
FOR TESTING TO ACM SERVICES, INC., ROCKVILLE, MD.

20. When did you first learn that the Grace product for which you are making this claim contained asbestos?

3000

Year

21. How did you first learn that the Grace product for which you are making the claim contained asbestos?

TESTING COMPANY REPORTED POSITIVE RESULT

22. Have you or someone on your behalf made an effort to remove, contain and/or abate the Grace product for which you are making this claim?

☒ Yes ☐ No

If Yes, attach all documents relating or referring to such efforts. If the documents are too voluminous to attach, attach a summary of the documents indicating the name of each document, date of each document, a brief description of the document, the location of the document, and who has possession and control of the document.

If you provide a summary of documents rather than the documents themselves, you are required to consent to the production and release of those documents to Grace upon Grace's further request.

23. If you do not have any such documents, explain why not and indicate who may have possession and control of such documents with respect to the property.

24. If you or someone on your behalf did not make an effort to remove, contain and/or abate the Grace product(s) for which you are making a claim, to the best of your knowledge, did anyone else make such an effort?

☐ Yes ☐ No

9276104

SERIAL #: